



Marine Safety Office
Charleston, SC
Photograph

Site: Cummins Eng
Break: 17.4
Other: v 2



Photo Number: 7

MV Case#: MV00004649

Unit Case#: 121-00

Date/Time: 17 November 2000 /~1730

Film Type: Digital

Photographer: MST2 Jason Kelley

Location: Cummins Engine Company, Charleston, SC

Vessel/Facility: Cummins Engine Company

Photo Description: Picture of drain, oil visible in drain.



10451234

Name: Anthony Wescott

Rank: E-6/MST1

Position: Pollution Investigator

Case: MV00004649

Enclosure (7)



Marine Safety Office
Charleston, SC
Photograph



Photo Number: 3

MV Case#: MV00004649

Unit Case#: 121-00

Date/Time: 17 November 2000 / ~1644

Film Type: Digital

Photographer: MST2 Jason Kelley

Location: Cummins Engine Company, Charleston, SC

Vessel/Facility: Cummins Engine Company

Photo Description: Stormwater ditch adjacent to Cummins property, located above previous pictures. Corrugated pipe visible on left hand side leads to stormwater manhole located on Cummins Property. Dark oil visible in center of picture.

Name: Anthony Wescott

Rank: E-6/MST1

Position: Pollution Investigator

Case: MV00004649

Enclosure (7)



Marine Safety Office
Charleston, SC
Photograph



Photo Number: 2

MV Case#: MV00004649

Unit Case#: 121-00

Date/Time: 17 November 2000 / ~1635

Film Type: Digital

Photographer: MST2 Jason Kelley

Location: Cummins Engine Company, Charleston, SC

Vessel/Facility: Cummins Engine Company

Photo Description: Stormwater ditch adjacent to Cummins property, two sections of adsorbent boom are visible in center of picture.

Name: Anthony Wescott

Rank: E-6/MST1

Position: Pollution Investigator

Case: MV00004649

Enclosure (7)



Marine Safety Office
Charleston, SC
Photograph



Photo Number: 4

MV Case#: MV00004649

Unit Case#: 121-00

Date/Time: 17 November 2000 / ~1655

Film Type: Digital

Photographer: MST2 Jason Kelley

Location: Cummins Engine Company, Charleston, SC

Vessel/Facility: Cummins Engine Company

Photo Description: Stormwater ditch adjacent to Cummins property, close-up of oil from picture 3.

Name: Anthony Wescott

Rank: E-6/MST1

Position: Pollution Investigator

Case: MV00004649

Enclosure (7)



Marine Safety Office
Charleston, SC
Photograph



Photo Number: 1

MV Case#: MV00004649

Unit Case#: 121-00

Date/Time: 17 November 2000 / ~1630

Film Type: Digital

Photographer: MST2 Jason Kelley

Location: Cummins Engine Company, Charleston, SC

Vessel/Facility: Cummins Engine Company

Photo Description: Stormwater ditch adjacent to Cummins property, two sections of adsorbent boom are visible in center of picture.

Name: Anthony Wescott

Rank: E-6/MST1

Position: Pollution Investigator

Case: MV00004649

Enclosure (7)



Marine Safety Office
Charleston, SC
Photograph



Photo Number: 6

MV Case#: MV00004649

Unit Case#: 121-00

Date/Time: 17 November 2000 /~1715

Film Type: Digital

Photographer: MST2 Jason Kelley

Location: Cummins Engine Company, Charleston, SC

Vessel/Facility: Cummins Engine Company

Photo Description: Close-up of drain.

Name: Anthony Wescott

Rank: E-6/MST1

Position: Pollution Investigator

Case: MV00004649

Enclosure (7)



Marine Safety Office
Charleston, SC
Photograph



Photo Number: 5

MV Case#: MV00004649

Unit Case#: 121-00

Date/Time: 17 November 2000 /~1703

Film Type: Digital

Photographer: MST2 Jason Kelley

Location: Cummins Engine Company, Charleston, SC

Vessel/Facility: Cummins Engine Company

Photo Description: Storage area behind Cummins wastewater treatment building.

Name: Anthony Wescott
Rank: E-6/MST1
Position: Pollution Investigator
Case: MV00004649

Enclosure (7)